

Serial No. 10/729,288

## AMENDMENTS TO THE ABSTRACT OF THE DISCLOSURE

A protector for vehicles' door openings with hingedly mounted doors to cover an adjacent area and protect is from rain and snow. The protector includes at least one frustro-conical roller member with a rollable sheet. The rollable sheet has two straight lateral ends and two curved lateral ends. Male and female hook members means for removably mounting ~~said second lateral~~ one of the straight lateral ends ~~end~~ to the upper end of ~~said the~~ door so that when ~~said the~~ door is swung open ~~said the~~ rollable sheet is unrolled substantially covering the area adjacent to ~~said the~~ door's opening. Each frustro-conical roller member includes spring bias assembly for urging the rolling back of the rollable sheet after being rolled out. When at least two roller members and at least two rollable sheets are contiguous, the rollable sheets include a zipper member means for releasably joining the contiguous curved lateral ends.

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**